



# Product Change Notice

PCN Number: 16-0105-02  
Issue Date: 30-MARCH-2016

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

<b>PRODUCTS AFFECTED:</b>	SP3224ECA-L/TR	SP3224ECA-L	SP3224ECY-L/TR	SP3224ECY-L
	SP3224EEA-L/TR	SP3224EEA-L	SP3224EEY-L/TR	SP3224EEY-L
	SP3495EEN-L/TR	SP3495EEN-L	SP3496EEN-L/TR	SP3496EEN-L
	SP3497EEN-L/TR	SP3497EEN-L	SP3225ECA-L/TR	SP3225ECA-L
	SP3225ECY-L/TR	SP3225ECY-L	SP3225EEA-L/TR	SP3225EEA-L
	SP3225EEY-L/TR	SP3225EEY-L		

**CHANGE CATEGORY:**

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate Foundry		

**DESCRIPTION OF CHANGE:**  
Qualification of alternate foundry subcon, Silan, in addition to previously qualified foundry subcon, Episil.

**IMPACT OF CHANGE:**  
There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 30-JUNE-2016

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**  
THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.