



# Product Change Notice

PCN Number: 16-1149-02  
Issue Date: 15-FEBRUARY-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:** Please refer to pages 2 to 4.

**CHANGE CATEGORY:**

- |   |                                    |   |
|---|------------------------------------|---|
| <input type="checkbox"/> Material                         | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                           | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Site |                                    |   |

**DESCRIPTION OF CHANGE:**

Qualification of alternate assembly subcon, ANST.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 15-MAY-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.



# Product Change Notice

PCN Number: 16-1149-02  
Issue Date: 15-FEBRUARY-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: customersupport@exar.com

**PRODUCTS AFFECTED:**

LP2951CS-L-5-0/TR	SP3232EBCN-L/TR	SP813LEN-L	XR3160EIU-F
SP1485ECN-L/TR	SP3232EBCN-L	SPX2951ACS-L-5-0/TR	XR3160EIUTR-F
SP1485ECN-L	SP3232EUCN-L/TR	SPX2951ACS-L-5-0	XR33032ID-F
SP1490ECN-L/TR	SP3232EUCN-L	SPX2954AS-L-5-0/TR	XR33032IDTR-F
SP1490ECN-L	SP3232EUEA-L/TR	SPX2954S-L-3-3/TR	XR33035ID-F
SP206CA-L/TR	SP3238ECY-L/TR	SPX2954S-L-5-0/TR	XR33035IDTR-F
SP207EEA-L/TR	SP3238EEA-L/TR	SPX3819S-L/TR	XR33038ID-F
SP208CA-L/TR	SP3238EEA-L	SPX3819S-L-1-2/TR	XR33038IDTR-F
SP208CA-L	SP3238EEY-L/TR	SPX3819S-L-1-5/TR	XR620AIS08
SP208EA-L/TR	SP3238EEY-L	SPX3819S-L-1-8/TR	XR620AIS08MTR
SP208ECA-L/TR	SP3244ECY-L/TR	SPX3819S-L-2-5/TR	XR8051ASO8MTR
SP208ECA-L	SP3244ECY-L	SPX3819S-L-3-3/TR	XR8051ASO8X
SP208EEA-L/TR	SP3249EEY-L/TR	SPX3819S-L-5-0/TR	XR8052ASO8MTR
SP208EEA-L	SP3249EEY-L	SPX385AS-L-1-2/TR	XR8052ASO8X
SP211CA-L/TR	SP330EEY-L/TR	XR1008ISO8	XR8054ASO14MTR
SP211EHEA-L/TR	SP330EEY-L	XR1008ISO8MTR	XR8054ASO14X
SP213EEA-L/TR	SP337EBCY-L/TR	XR1008ISO8X	XR8054ATP14
SP2525A-1EN-L/TR	SP337EBCY-L	XR1009ISO8	XR8054ATP14MTR
SP2525A-2EN-L/TR	SP337EUCY-L/TR	XR1009ISO8MTR	XR8054ATP14X
SP2526A-2EN-L/TR	SP337EUCY-L	XR1009ISO8X	XR81101-AA02-F
SP26LV431CN-L/TR	SP337EUEY-L/TR	XR2008ISO8	XR81101-AA02TR-F
SP26LV431CN-L	SP337EUEY-L	XR2008ISO8MTR	XR81101-F
SP3070EMN-L/TR	SP34063AEN-L/TR	XR2008ISO8X	XR81102-CA02-F
SP3070EMN-L	SP3483CN-L/TR	XR2009ISO8	XR81102-CA02TR-F
SP3071EEN-L/TR	SP3483CN-L	XR2009ISO8MTR	XR81102-F
SP3071EEN-L	SP3483EN-L/TR	XR2009ISO8X	XRA1200IG16-F
SP3071EMN-L/TR	SP3483EN-L	XR20M1170IG24-F	XRA1200IG16TR-F
SP3071EMN-L	SP3485CN-L/TR	XR20M1170IG24TR-F	XRA1201PIG24-F
SP3072EMN-L/TR	SP3485CN-L	XR22404CG28TR-F	XRA1201PIG24TR-F
SP3072EMN-L	SP3490CN-L/TR	XR3070XED-F	XRA1202IG16-F
SP3073EEN-L/TR	SP3490EN-L/TR	XR3070XEDTR-F	XRA1202IG16TR-F

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.



# Product Change Notice

PCN Number: 16-1149-02  
Issue Date: 15-FEBRUARY-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

SP3073EEN-L	SP3490EN-L	XR3070XID-F	XRA1203IG24-F
SP3073EMN-L/TR	SP3494EN-L/TR	XR3071XED-F	XRA1203IG24TR-F
SP3073EMN-L	SP3494EN-L	XR3071XEDTR-F	XRA1206IG16-F
SP3074EEN-L/TR	SP3495EEN-L/TR	XR3071XID-F	XRA1206IG16TR-F
SP3074EEN-L	SP3495EEN-L	XR3071XIDTR-F	XRA1207IG24-F
SP3074EMN-L/TR	SP385ECA-L/TR	XR3072XED-F	XRA1207IG24TR-F
SP3074EMN-L	SP385ECA-L	XR3072XEDTR-F	XRA1402IG16-F
SP3075EEN-L/TR	SP4082EEN-L/TR	XR3072XID-F	XRA1402IG16TR-F
SP3075EEN-L	SP4082EEN-L	XR3072XIDTR-F	XRA1403IG24-F
SP3075EMN-L/TR	SP481ECN-L/TR	XR3073XED-F	XRA1403IG24TR-F
SP3075EMN-L	SP481ECN-L	XR3073XEDTR-F	XRA1404IG16-F
SP3076EEN-L/TR	SP483CN-L/TR	XR3073XID-F	XRA1404IG16TR-F
SP3077EMN-L/TR	SP483CN-L	XR3074XED-F	XRA1405IG24-F
SP3077EMN-L	SP483EN-L/TR	XR3074XEDTR-F	XRA1405IG24TR-F
SP3078EMN-L/TR	SP483EN-L	XR3074XID-F	XRP2525IDTR-1-F
SP3078EMN-L	SP490ECN-L/TR	XR3074XIDTR-F	XRP2525IDTR-2-F
SP3080EEN-L/TR	SP490ECN-L	XR3075XED-F	XRP2526IDTR-2-F
SP3080EEN-L	SP490EEN-L/TR	XR3075XEDTR-F	XRP7613IDBTR-F
SP3080EMN-L	SP490EEN-L	XR3075XID-F	XRP7664IDTR-F
SP3081EEN-L/TR	SP6123ACN-L/TR	XR3075XIDTR-F	XRT85L61IG-F
SP3081EEN-L	SP6128AEY-L/TR	XR3076XED-F	XRT91L33AIG-F
SP3082EMN-L	SP6128AEY-L	XR3076XEDTR-F	XRT91L33AIGTR-F
SP3083EEN-L/TR	SP6128AHY-L/TR	XR3076XID-F	SP1485EEN-L/TR
SP3083EEN-L	SP6660EN-L/TR	XR3077XED-F	SP1486EEN-L/TR
SP3084EEN-L/TR	SP690ACN-L/TR	XR3077XEDTR-F	SP3070EEN-L/TR
SP3084EEN-L	SP690ACN-L	XR3078XED-F	SP3070EEN-L
SP3084EMN-L	SP690AEN-L/TR	XR3078XEDTR-F	SP3072EEN-L/TR
SP3085EEN-L/TR	SP690AEN-L	XR3080XED-F	SP3072EEN-L
SP3085EEN-L	SP690SCN-L/TR	XR3080XEDTR-F	SP3076EEN-L
SP3085EMN-L	SP690SEN-L/TR	XR3080XID-F	SP3076EMN-L/TR
SP3086EEN-L/TR	SP690TEN-L/TR	XR3080XIDTR-F	SP3076EMN-L
SP3086EEN-L	SP690TEN-L	XR3081XED-F	SP3077EEN-L/TR
SP3087EEN-L/TR	SP691ACN-L/TR	XR3081XEDTR-F	SP3077EEN-L
SP3087EEN-L	SP691ACN-L	XR3081XID-F	SP3078EEN-L/TR
SP3203ECY-L/TR	SP691AEN-L/TR	XR3081XIDTR-F	SP3078EEN-L

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.



# Product Change Notice

PCN Number: 16-1149-02  
Issue Date: 15-FEBRUARY-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

SP3203EEY-L/TR	SP691AEN-L	XR3082XED-F	SP3082EEN-L/TR
SP3203EEY-L	SP705CN-L/TR	XR3082XEDTR-F	SP3082EEN-L
SP3220EBEA-L	SP705CN-L	XR3083XED-F	SP3088EEN-L/TR
SP3220ECA-L/TR	SP705EN-L/TR	XR3083XEDTR-F	SP3088EEN-L
SP3220ECA-L	SP705EN-L	XR3083XID-F	SP3232EBEN-L/TR
SP3221ECA-L/TR	SP706EN-L/TR	XR3083XIDTR-F	SP3232EBEN-L
SP3221ECA-L	SP706RCN-L/TR	XR3084XED-F	SP3232ECN-L/TR
SP3222EBEA-L/TR	SP706REN-L/TR	XR3084XEDTR-F	SP3232ECN-L
SP3222EEA-L/TR	SP706REN-L	XR3084XID-F	SP3232EEN-L/TR
SP3222EEA-L	SP706SCN-L/TR	XR3084XIDTR-F	SP3232EEN-L
SP3222EEY-L/TR	SP706SEN-L/TR	XR3085XED-F	SP3485EN-L/TR
SP3222EEY-L	SP706SEN-L	XR3085XEDTR-F	SP3485EN-L
SP3222EUEY-L/TR	SP706TCN-L/TR	XR3086XED-F	SP481EEN-L/TR
SP3222EUEY-L	SP707CN-L/TR	XR3086XEDTR-F	SP481EEN-L
SP3223EBEA-L/TR	SP707CN-L	XR3086XID-F	XR3077XID-F
SP3223ECY-L/TR	SP708CN-L/TR	XR3086XIDTR-F	XR3077XIDTR-F
SP3223ECY-L	SP708EN-L/TR	XR3087XED-F	XR3078XID-F
SP3223EUCY-L/TR	SP708REN-L/TR	XR3087XEDTR-F	XR3078XIDTR-F
SP3223EUCY-L	SP708SCN-L/TR	XR3087XID-F	XR3082XID-F
SP3224EEA-L/TR	SP708SEN-L/TR	XR3087XIDTR-F	XR3082XIDTR-F
SP3224EEA-L	SP708TCN-L/TR	XR3088XED-F	XR3085XID-F
SP3224EEY-L/TR	SP78L05N-L/TR	XR3088XEDTR-F	XR3085XIDTR-F
SP3225EEY-L/TR	SP791CN-L/TR	XR3160ECU-F	XR3088XID-F
SP3226EEY-L/TR	SP813LEN-L/TR	XR3160ECUTR-F	XR3088XIDTR-F
SP3227EEY-L/TR			

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.