



# Product Change Notice

PCN Number: 14-0939-01  
Issue Date: 12-JANUARY-2015

**Exar Corporation**

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP3243EBCA-L	SP3243EBCA-L/TR	SP3243EBCR-L	SP3243EBCR-L/MTR
SP3243EBCR-L/TR	SP3243EBCY-L	SP3243EBCY-L/TR	SP3243EBEA-L
SP3243EBEA-L/TR	SP3243EBEY-L	SP3243EBEY-L/TR	SP3243ECA-L
SP3243ECA-L/TR	SP3243ECT-L	SP3243ECT-L/TR	SP3243ECY-L
SP3243ECY-L/TR	SP3243EEA-L	SP3243EEA-L/TR	SP3243EET-L
SP3243EET-L/TR	SP3243EEY-L	SP3243EEY-L/TR	SP3243EHCA-L
SP3243EHCA-L/TR	SP3243EHCT-L	SP3243EHCT-L/TR	SP3243EHCY-L
SP3243EHCY-L/TR	SP3243EHEA-L	SP3243EHEA-L/TR	SP3243EHET-L
SP3243EHET-L/TR	SP3243EHEY-L	SP3243EHEY-L/TR	SP3243EUCA-L
SP3243EUCA-L/TR	SP3243EUCT-L	SP3243EUCT-L/TR	SP3243EUCY-L
SP3243EUCY-L/TR	SP3243EUEA-L	SP3243EUEA-L/TR	SP3243EUET-L
SP3243EUET-L/TR	SP3243EUEY-L	SP3243EUEY-L/TR	

**CHANGE CATEGORY:**

Material
  Process
  Package  
 Design
  Datasheet
  Packing/Shipping  
 Other: Alternate Foundry and Assembly Site

**DESCRIPTION OF CHANGE:**

Qualification of alternate foundry site, TSMC, using 0.25um CMOS process.  
Qualification of alternate assembly site, Greatek, Taiwan for assembly using either copper or gold wire-bond.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 13-APRIL-2015

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.