

September 2005

MIGRATING FROM THE XR17D15X TO THE XR17V25X

Author: PY

1.0 INTRODUCTION

This application note describes the changes necessary and what to consider when migrating from the XR17D15x to the XR17V25x.

2.0 HARDWARE DIFFERENCES

Because the XR17D15x is PCI 2.2 compliant and the XR17V25x is PCI 3.0 compliant, there are some hardware changes to consider when migrating from the XR17D15x to the XR17V25x. In addition, there are some hardware differences because the XR17V25x has some new and enhanced features. Sections 2.1-2.4 below lists the hardware differences between the XR17D15x and the XR17V25x.

2.1 VCC/VIO

The VCC and VIO signals were separate on the XR17D15x because the core voltage (VCC) could be operating at a different voltage than the I/O voltage (VIO). For an add-in card example, VCC could be at 5V while VIO could be either 3.3V or 5V depending on whether it was plugged into a 3.3V slot or a 5V slot. There are no separate VIO and VCC signals for the XR17V25x because it is a 3.3V only PCI UART. The XR17V25x is 3.3V only because there are no 5V specifications in PCI 3.0.

TABLE 1: VOLTAGE REQUIREMENTS

DEVICE FAMILY	CORE VOLTAGE	I/O VOLTAGE
XR17D15x	3.3V or 5V	3.3V or 5V
XR17V25x	3.3V Only	3.3V Only

2.2 PCI CLOCK

The XR17D15x can operate with a PCI clock of up to 33 MHz while the XR17V25x can operate with a PCI clock of up to 66 MHz. To operate at 66 MHz, the M66EN signal on the PCI bus should be connected to VCC.

TABLE 2: MAXIMUM PCI CLOCK FREQUENCY

DEVICE FAMILY	MAX PCI CLOCK FREQUENCY
XR17D15x	33 MHz
XR17V25x	66 MHz

2.3 BAUD RATE (OR DATA RATE)

The XR17V25x operates at a faster data rate than the XR17D15x. With an 8X sampling rate, the XR17V25x can operate up to more than 8Mbps while the XR17D15x could only operate up to 6.25Mbps.

TABLE 3: MAXIMUM BAUD RATE (DATA RATE)

DEVICE FAMILY	MAX EXTERNAL CLOCK FREQUENCY	MAX BAUD RATE
XR17D15x	50 MHz	6.25 Mbps
XR17V25x	66 MHz	8.25 Mbps

2.4 PIN DIFFERENCE

The TEST# pin (input pin used for factory test mode) in the XR17D15x has been changed to the PME# pin (open-drain output pin) in the XR17V25x to support Power Management. The XR17V25x is compliant with Power Management Revision 1.1 Specifications. The XR17D15x did not have any Power Management support. If Power Management is used, then the PME# pin should be connected to the PME# signal on the PCI bus interface. Otherwise, the PME# pin should be pulled-up or left floating.

3.0 FIRMWARE DIFFERENCES

The internal register set of the XR17V25x is based on the internal register set of the XR17D15x. However, there were some changes/enhancements in the XR17V25x that resulted in some changes in the internal register set. Here is a list of the changes/enhancements and how the register set was affected.

3.1 FRACTIONAL BAUD RATE GENERATOR

Traditionally, the baud rate divisor is a value between 1 and 32767 (or $2^{16} - 1$) that is programmed via two 8-bit registers (DLL and DLM). With these divisors, standard baud rates such as 9600 bps or 115200 bps could be achieved by using standard clock/crystal frequencies such as 1.8432 MHz or 14.7456 MHz. Use the following formula to calculate the baud rate divisor:

$$\text{divisor (decimal)} = (\text{clock frequency}) / (\text{baud rate} \times \text{sampling rate})$$

By default the sampling rate is 16X the clock frequency, unless the 8X sampling rate is enabled via the 8XMODE register. For example, if the desired baud rate is 115200 bps and a 14.7456 MHz clock is used, the divisor would be 8. Using these standard clock frequencies, the standard baud rates were easily achieved. However, when non-standard clock frequencies such as 10 MHz or 24 MHz were used, some standard baud rates were not possible because the divisors are not whole numbers. Using the closest whole number divisor still resulted in data transmission errors because the baud rate deviation was greater than the deviation tolerated by the UART (see DAN108 for complete details).

For example, if the desired baud rate is 115200 bps and a 10 MHz clock is used, the approximate divisor would be 5.425. The table below shows the two closest divisors and the corresponding data rate error.

TABLE 4: BAUD RATE ERROR IN XR17D15X

DESIRED BAUD RATE (BPS)	DLM	DLL	DLD	ACTUAL BAUD RATE	% ERROR
115200	0x00	0x05	N/A	125000	8.5
115200	0x00	0x06	N/A	104167	9.6

In the XR17V25x, a DLD register was added to allow fractional divisors. The value programmed into DLD would be divided by 16 and then added to the divisor. Using the same example above, the the closest divisor would be 5 and the DLD would be 7. This would result in a divisor of 5.4375. As you can see below, the resulting baud rate would be within the baud rate deviation tolerated by the UART. .

TABLE 5: BAUD RATE ERROR IN XR17V25X

DESIRED BAUD RATE (BPS)	DLM	DLL	DLD	ACTUAL BAUD RATE	% ERROR
115200	0x00	0x05	0x07	114953	0.2

The addition of the DLD register allows more flexibility in the clock frequency that can be used with the XR17V25x to generate almost any desired baud rate. Also, if the system has a clock available, the XR17V25x can use that instead of a separate crystal.

3.2 DEVICE ID

To distinguish between the two families and their capabilities, the Device ID for the XR17V25x family is different. The upper nibble of the Device ID distinguishes between the two families. The lower nibble indicates how many UART channels there are on the device. The table below lists the Device IDs.

TABLE 6: DEVICE IDs

DEVICE	DEVICE ID	DEVICE	DEVICE ID
XR17D152	0x22	XR17V252	0x42
XR17D154	0x24	XR17V254	0x44
XR17D158	0x28	XR17V258	0x48

In the Windows drivers provided by Exar, the driver does check for the Device ID. When migrating from the XR17D15x to the XR17V25x, the software driver should be updated to detect the new Device IDs. Otherwise, the drivers will not install properly.

3.3 POWER MANAGEMENT

Power Management registers were added at address offsets 0x40 and 0x44 in the PCI Local Bus Configuration space to support the Power Management feature in the XR17V25x. See the XR17V25x datasheet for complete details. This feature was not available in the XR17D15x.

3.4 EEPROM ADDRESS DEFINITIONS

The XR17D15x only expects to read four 16-bit values from the EEPROM. However, the XR17V25x expects to read eight 16-bit values from the EEPROM. Therefore, the EEPROM should be updated so that there are 8 16-bit values programmed into the EEPROM instead of 4. The table below lists the 16-bit values that the XR17D15x and XR17V25x UARTs expect.

TABLE 7: 16-BIT EEPROM DATA

EEPROM MEMORY ADDRESS	XR17D15x	XR17V25x
0x00	Vendor ID	Vendor ID
0x01	Device ID	Device ID
0x02	Subsystem Vendor ID	Class Code
0x03	Subsystem Device ID	Class Code (continued)
0x04	-	Subsystem Vendor ID
0x05	-	Subsystem Device ID
0x06	-	Special Register (Lower Word)
0x07	-	Special Register (Upper Word)

There is an EEPROM programming utility available from Exar that can program the EEPROM through the UART for the Windows 2000 or Windows XP operating system. However, to program the EEPROM through the UART, the Windows 2000/XP driver must first be installed. This driver is available to Exar customers after a Software License Agreement (SLA) has been completed. The Windows drivers and EEPROM programming utility can be obtained by sending an e-mail to uarttechsupport@exar.com.

3.5 TIMER/COUNTER

In the XR17D15x, each of the first 6 bits of the TIMERCNTL register had a function. However, the Timer/Counter functions were enhanced in the XR17V25x. In order to prevent simple errors of not masking the correct bits, the TIMERCNTL register is now command driven. A 4-bit command is used instead of each individu-

al bit. The table below lists the different Timer/Counter functions and how they are controlled in the XR17D15x and the XR17V25x. For a detailed description of the Timer/Counter, see the XR17V25x datasheet.

TABLE 8: TIMER/COUNTER FUNCTIONS

TIMER/COUNTER FUNCTION	XR17D15x (BIT DRIVEN)	XR17V25x (COMMAND DRIVEN)
Disable Timer/Counter Interrupt	TIMERCNTL[0] = 0	TIMERCNTL[3:0] = 0010
Enable Timer/Counter Interrupt	TIMERCNTL[0] = 1	TIMERCNTL[3:0] = 0001
Stop or Pause Timer/Counter	TIMERCNTL[1] = 0	TIMERCNTL[3:0] = 1010
Start Timer/Counter	TIMERCNTL[1] = 1	TIMERCNTL[3:0] = 1001
Select Re-Triggerable Mode	TIMERCNTL[2] = 0	TIMERCNTL[3:0] = 0100
Select One-Shot Mode	TIMERCNTL[2] = 1	TIMERCNTL[3:0] = 0011
Select Internal Crystal Oscillator as clock source for the Timer/Counter	TIMERCNTL[3] = 0	TIMERCNTL[3:0] = 0101
Select External Clock (via TMRCK input pin) as clock source for the Timer/Counter	TIMERCNTL[3] = 1	TIMERCNTL[3:0] = 0110
De-Route Timer output from MPIO[0] pin	TIMERCNTL[4] = 0	TIMERCNTL[3:0] = 1000
Route Timer output to MPIO[0] pin	TIMERCNTL[4] = 1	TIMERCNTL[3:0] = 0111
Reset Timer	-	TIMERCNTL[3:0] = 1011

3.6 TRANSMITTER AND RECEIVER DISABLE

The Transmitter and Receive can be disabled in the XR17V25x. This feature is not available in the XR17D15x. The Transmitter is disabled when MSR bit-3 = 1 (write-only). When the Transmitter is disabled, any data left or written into the TX FIFO will not be transmitted. It will resume transmission when MSR bit-3 has been reset. Similarly, the Receiver is disabled when MSR bit-2 = 1 (write-only). When the Receiver is disabled, it will ignore any data received during that time at the RX pin. It will receive data normally when MSR bit-2 has been reset. See the XR17V25x datasheet for complete details.

3.7 TXCHAR IMMEDIATE

TXCHAR Immediate is another new feature in the XR17V25x. One byte of data can be inserted into the Transmit Shift Register, ahead of any data that is remaining in the TX FIFO, after the current byte has shifted out. This is done by writing to MCR bit-3 (assuming EFR bit-4 = 1) and then writing to the THR register. This feature can only be used when the Transmitter has not been disabled. See the XR17V25x datasheet for complete details.

3.8 TX XON/XOFF INDICATOR

In the XR17D15x, the XCHAR register would indicate which flow control character (XON or XOFF) was received last by a particular channel. If bit-0 = 1, then the last flow control character received was an XOFF. If bit-1 = 1, then the last flow control character received was an XON. In addition to that, the XR17V25x has 2 additional bits to indicate whether the last flow control character transmitted was an XON or XOFF character. If XCHAR bit-2 = 1, then the last flow control character transmitted was an XOFF character. If XCHAR bit-3 = 1, then the last flow control character transmitted was an XON character.

4.0 CONCLUSION

The XR17V25x is an enhanced version of the XR17D15x with a faster PCI bus clock, higher data rate, and many new features. Because of these reasons, some hardware and software changes will be required to take advantage of the performance of the 66MHz PCI clock and the other enhanced features of the XR17V25x.

NOTICE

EXAR Corporation reserves the right to make changes to the products contained in this publication in order to improve design, performance or reliability. EXAR Corporation assumes no responsibility for the use of any circuits described herein, conveys no license under any patent or other right, and makes no representation that the circuits are free of patent infringement. Charts and schedules contained here in are only for illustration purposes and may vary depending upon a user's specific application. While the information in this publication has been carefully checked; no responsibility, however, is assumed for inaccuracies.

EXAR Corporation does not recommend the use of any of its products in life support applications where the failure or malfunction of the product can reasonably be expected to cause failure of the life support system or to significantly affect its safety or effectiveness. Products are not authorized for use in such applications unless EXAR Corporation receives, in writing, assurances to its satisfaction that: (a) the risk of injury or damage has been minimized; (b) the user assumes all such risks; (c) potential liability of EXAR Corporation is adequately protected under the circumstances.

Copyright 2005 EXAR Corporation

September 2005

Send your UART technical inquiry with technical details to hotline: uarttechsupport@exar.com

Reproduction, in part or whole, without the prior written consent of EXAR Corporation is prohibited.
