



Product Change Notice

PCN Number: 16-1146-02
Issue Date: 12-JANUARY-2017

Exar Corporation

www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:	SP619EK-L/TR	SP6205EM5-L-1-8/TR	SPX3819M5-L-2-5/TR	XR46084ESFTR-ADJ
	SP6201EM5-L/TR	SP6205EM5-L-2-5/TR	SPX3819M5-L-3-0/TR	SP809EK-L-2-3/TR
	SP6201EM5-L-1-5/TR	SP6205EM5-L-2-8/TR	SPX385AM-L-2-5/TR	SP809EK-L-2-6/TR
	SP6201EM5-L-1-8/TR	SP6205EM5-L-3-0/TR	SPX385AM-L-5-0/TR	SP809EK-L-2-9/TR
	SP6201EM5-L-2-5/TR	SP6205EM5-L-3-3/TR	SPX431LM1-L/TR	SP809EK-L-3-1/TR
	SP6201EM5-L-3-0/TR	SP6641AEK-L-3-3/TR	SPX432AM-L/TR	SP809EK-L-4-6/TR
	SP6201EM5-L-3-3/TR	SP6641AEK-L-5-0/TR	SPX432M-L/TR	SP809NEK-L-2-3/TR
	SP6201EM5-L-5-0/TR	SP6641BEK-L-3-3/TR	SPX5205M5-L-1-2/TR	SP809NEK-L-2-9/TR
	SP6203EM5-L/TR	SP6641BEK-L-5-0/TR	SPX5205M5-L-1-8/TR	SP809NEK-L-3-1/TR
	SP6203EM5-L-2-5/TR	SPX2431AM-L/TR	SPX5205M5-L-2-5/TR	SP809NEK-L-4-6/TR
	SP6203EM5-L-2-8/TR	SPX2431M-L/TR	SPX5205M5-L-3-0/TR	SP810EK-L-4-4/TR
	SP6203EM5-L-3-0/TR	SPX3819M5-L-1-2/TR	SPX5205M5-L-3-3/TR	SPX5205M5-L/TR
	SP6203EM5-L-3-3/TR	SPX3819M5-L-1-5/TR	SPX5205M5-L-5-0/TR	XRP6124ESTR0.5-F
	SP6205EM5-L/TR	SPX3819M5-L-1-8/TR	XR46083ESFTR-ADJ	XRP6124HVESTR0.5-F

CHANGE CATEGORY:

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input checked="" type="checkbox"/> Packing/Shipping
<input type="checkbox"/> Other:		

DESCRIPTION OF CHANGE:

Standard tape and reel quantity will change from 2500 pieces to 3000 pieces for SOT23-3L/5L/6L.

IMPACT OF CHANGE:

There is no change to product form, fit or function.

TARGET IMPLEMENTATION DATE: 12-APRIL-2017

Please contact customer support (customersupport@exar.com) for sample date availability or qualification data

PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.