

#### PROCESS CHANGE NOTICE (PCN) PCN Number: Means of distinguishing changed devices: 21072 Date Issued: October 3, 2023 Product Mark: Back Mark Date Effective: October 3, 2023 □ Date Code Date Issued (+90 days): January 3, 2024 X Lot number Attachment: Yes No ⊠

## **Product(s) Affected:**

XR79103EL-F	XR79110EL-F	XR79120EL-F	XR79206EL-F
XR79106EL-F	XR79115EL-F	XR79203EL-F	

#### **Description of Change:**

MaxLinear has qualified ATX Group, Suzhou (ATXSZ) assembly site for the part numbers listed above. Please note bill of material (BOM) changes in the Change Details section below.

There is no change to form, fit, function and reliability of the parts.

#### **Purpose of Change:**

Assembly supplier, UTAC Dongguan, will no longer support SIP QFN.

### **Change Details:**

ltem	Current	New/Additional
Manufacturing site	Assembly: UTAC, Dong Guan	Assembly: ATX Group, Suzhou
BOM: Solder Paste	Indium 3.2 Sn90Sb10 Sanju M10 Sn95Sb5	Senju M705
ВОМ: Ероху	Henkel Ablestik 8200T	Henkel QMI519
BOM: Mold Compound	Sumitomo G770HJ Hitachi CEL9220HF	Sumitomo G311Q-L

### **Reliability/Qualification Summary:**

Available upon request. Contact our Customer Support team by creating a support ticket at <a href="http://www.maxlinear.com/support/createcase">http://www.maxlinear.com/support/createcase</a>



# **Samples and Support**

Contact our Customer Support team by creating a support ticket at <a href="http://www.maxlinear.com/support/createcase">http://www.maxlinear.com/support/createcase</a>

Phone: 1-760-692-0711

Customers are advised to acknowledge receipt of this r notice. Lack of acknowledgement within 30 days constitution.	· · · · · · · · · · · · · · · · · · ·			
Please email this form to the contact above after completing the following information:				
Customer:				
Name:				
Title:				
Date:				
E-Mail:				
Phone:				
Fax:				
Approval for shipments prior to effective date				
Customer Comments (Optional):				