



| PROCESS CHANGE NOTICE (PCN) | | |
|------------------------------------|-------------------|--|
| PCN Number: | PCN-23011A | Means of distinguishing changed devices: <input type="checkbox"/> Product Mark: <input type="checkbox"/> Back Mark <input type="checkbox"/> Date Code <input checked="" type="checkbox"/> No change to device Attachment: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| Date Issued: | June 1, 2023 | |
| Date Effective: | June 1, 2023 | |
| Date Issued (+90 days): | August 29, 2023 | |

Product(s) Affected: Exar Legacy | MaxLinear HPA Products

| | | | | | | | | | | | |
|----------------|----------------------------|---|---------------|-----------------|---------------|----------------|---------|---------------|----------------|-----------|--|
| | EXAR Legacy product | Part number prefix LP, SP, SPX, XR, XRA, XRP, XRT, ST, VRC Products: 9240CB-F, DX204001 | | | | | | | | | |
| | MXL HPA products | Part number prefix: New MXL products Products (existing): <table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="width: 50%;">MXL7218-ABA-T</td> <td style="width: 50%;">MXL7225-1-ABA-T</td> </tr> <tr> <td>MXL7225-ABA-T</td> <td>MXL76125-AQB-R</td> </tr> <tr> <td>MXL7630</td> <td>MXL7704-BQB-T</td> </tr> <tr> <td>MXL83947-AQB-R</td> <td>MXL8908A1</td> </tr> </tbody> </table> | MXL7218-ABA-T | MXL7225-1-ABA-T | MXL7225-ABA-T | MXL76125-AQB-R | MXL7630 | MXL7704-BQB-T | MXL83947-AQB-R | MXL8908A1 | |
| MXL7218-ABA-T | MXL7225-1-ABA-T | | | | | | | | | | |
| MXL7225-ABA-T | MXL76125-AQB-R | | | | | | | | | | |
| MXL7630 | MXL7704-BQB-T | | | | | | | | | | |
| MXL83947-AQB-R | MXL8908A1 | | | | | | | | | | |

Description of Change:

In 2023, MaxLinear will be converting all shipping labels for the parts noted from an EXAR format to MaxLinear's label. During this transition customers may receive either label.

This change affects only shipping and packing labels. This change will not affect the part number, part marking, manufacturing process or manufacturing sites.

Only work in progress material will be converted. Existing inventory from MaxLinear's warehouse, channel sales, distributor, and such, will not be converted. Hence, customers may experience receiving mixed shipments with both Exar and MaxLinear labels for some period until existing inventory of old labels is eventually cleared out. Situation is product to product with no predictable way to determine when all old labels will be exhausted.

No change to product form, fit, function and reliability.









ADDENDUM: Fixed MBB label logo for DX204001 to MaxLinear logo.

Purpose of Change:

Standardize MaxLinear shipping labels.



Change Details:

| Item | Current | New/Additional |
|------------------------------|---|--|
| Affected part: DX204001 only | <p>MBB bag</p>  | <p>MBB bag</p>  |
| Affected part: DX204001 | <p>Outer box label</p>  | <p>Outer box label</p>  |
| ALL OTHER affected products | <p>Reel, MBB bag, Inner box label</p>  | <p>Reel MBB bag, Inner box label</p>  |
| ALL OTHER affected products | <p>Outer box label</p>  | <p>Outer box label</p>  |



Reliability/Qualification Summary:

<Not applicable>

Samples and Support

Contact our Customer Support team by creating a support ticket at

<http://www.maxlinear.com/support/createcase>

Phone: 1-760-692-0711

Customers are advised to acknowledge receipt of this notification within 30 days of delivery of the notice. Lack of acknowledgement within 30 days constitutes acceptance of this change without further action.

Please email this form to the contact above after completing the following information:

Customer: _____

Name: _____

Title: _____

Date: _____

E-Mail: _____

Phone: _____

Fax: _____

Approval for shipments prior to effective date

Customer Comments (Optional):