



Subject: Product Discontinuation Notification

To whom it may concern,

This is notification that the part numbers listed below will be discontinued by Exar Corporation:

| Ordering Part Number | Suggested Part Replacement | Functional Equivalent | Pin Compatible | Comments |
|----------------------|----------------------------|-----------------------|----------------|----------|
| 392-10062 | None | | | |
| 392-10063 | None | | | |
| 392-10070 | None | | | |
| 392-10088 | None | | | |
| 8201CB-F | None | | | |
| 8202CB-F | None | | | |
| CAB-00004-002 | None | | | |
| CAB-00005-002 | None | | | |
| CAB-M2S-39-39-5 | None | | | |
| DX1710A01 | None | | | |
| DX1720A01 | None | | | |
| DX1730A01 | None | | | |
| GX174111 | None | | | |
| OEM-IPM7110 | None | | | |
| OEM-IPM7120 | None | | | |
| OEM-SY136 | None | | | |
| SW-LIC-IDE | None | | | |



PDN No: 17-0623-03
Issue Date: 21-JULY-2017

Purchase orders will be accepted as indicated below on a non-cancellable, non-returnable basis provided there is inventory remaining at the time of order placement. ** Subject to product availability. No reschedules will be allowed.

| | |
|-------------------------|------------------|
| Last order date: | January 22, 2018 |
| Last ship date: | July 20, 2018 |

Please check inventory availability with your distributor or Exar Customer Service Representative before attempting to place an order.

Note to distributors: All LTB purchase orders must be submitted manually.

If you should have any questions regarding this notice, please contact Lisa Bedard via email at lbedard@maxlinear.com or customersupport@exar.com.